

# Radiator Cooling Panel PART# 908-215 & 908-216

## Installation Instructions 1999-2005 Miata

440 Rutherford St. Goleta, CA 93117 1-800-667-7872 • FAX 805-692-2525 • www.MossMotors.com



| Ref | Quantity | Part #             | Description                        |
|-----|----------|--------------------|------------------------------------|
| 1a  | 4        | 053-157            | BHCS, FLANGED, M6 X 1.0 X 16       |
| 1b  | 4        | 053-156            | SPACER, COOLING PANEL              |
| 1c  | 2        | 053-158            | NUT, FLANGED M8 X 1.25             |
| 1d  | 1        | 773-005 or 773-025 | PANEL, RADIATOR COOLING *not shown |

#### Read and understand these instructions before begging the installation.

Images may vary from actual product.

#### Installation instructions:

- 1) Open and prop the hood. Let the radiator cool to ambient temperature.
- Remove the two top radiator securing brackets. 2)



### Installation Instructions

Remove the headlight bolts closest to the center 3) of the car. Remove the front fascia support bolts adjacent to the previously removed headlight bolts.



4) Set a spacer on the each of the four empty bolt holes.




Figure 4

Set the cooling panel on the car while keeping the 5) spacers aligned with the bolt holes. Use the provided hardware to secure the panel to the car. Install the upper radiator mounting brackets. Snug all fasteners down to final torque.



Check the hood for rubber bumpers. If it has them, 6) they will need to be trimmed (shortened) or removed all together to allow the hood to close properly. The cooling panel sits up a bit higher than the factory touch point for these bumpers.



## Designed and Distributed by Moss Motors, Ltd.

For questions or comments please contact:

# Moss Motors, Ltd.

440 Rutherford Street, Goleta, California 93117 In the US & Canada Toll Free (800) 667-7872 LOCAL (805) 681-3400 FAX (805) 692-2510



Moss Europe Ltd. Unit 16 Hampton Business Park Bolney Way Feltham TW13 6DB, United Kingdom In the UK: 020-8867-2020 FAX: 020-8867-2030